

# Rules and Regulations

Federal Register

Vol. 88, No. 50

Wednesday, March 15, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-0435; Project Identifier AD-2023-00384-E; Amendment 39-22385; AD 2023-05-16]

RIN 2120-AA64

#### Airworthiness Directives; Continental Aerospace Technologies, Inc., Reciprocating Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2023-04-08 which applied to certain Continental Aerospace Technologies, Inc. (Continental) GTSIO-520-C, -D, -H, -K, -L, -M, -N, and -S; IO-360-A, -AB, -AF, -C, -CB, -D, -DB, -E, -ES, -G, -GB, -H, -HB, -J, -JB, -K, and -KB; IO-470-D, -E, -G, -H, -J, -K, -L, -M, -N, -P, -R, -S, -T, -U, -V, and -VO; IO-520-A, -B, -BA, -BB, -C, -CB, -D, -E, -F, -J, -K, -L, -M, and -MB; IO-550-A, -B, -C, -D, -E, -F, -G, -L, -N, -P, and -R; LTSIO-360-E, -EB, -KB, and -RB; LTSIO-520-AE; O-470-A, -B, -E, -G, -H, -J, -K, -L, -M, -N, -R, -S, -T, and -U; TSIO-360-A, -AB, -B, -BB, -C, -CB, -D, -DB, -E, -EB, -G, -GB, -H, -HB, -JB, -KB, -LB, -MB, -RB, and -SB; TSIO-520-A, -AE, -AF, -B, -BB, -BE, -C, -CE, -D, -DB, -E, -EB, -G, -H, -J, -JB, -K, -KB, -L, -LB, -M, -NB, -P, -R, -T, -UB, -VB, and -WB; TSIO-550-A, -B, -C, -E, -G, -K, and -N; TSIOF-550-K; and TSIO-550-A, -B, and -C model reciprocating engines. AD 2023-04-08 required inspection of the crankshaft assembly for proper installation of the counterweight retaining rings in the counterweight groove and, depending on the results of the inspection, corrective actions if improper installation was found. This AD continues to require inspection of

the crankshaft assembly for proper installation of the counterweight retaining rings in the counterweight groove, and corrective actions if improper installation is found. Since the FAA issued AD 2023-04-08, operators notified the FAA, and Continental confirmed, that certain affected model reciprocating engines not included in the applicability of AD 2023-04-08 are also affected by the unsafe condition. Additionally, the FAA determined the special flight permit paragraph required revision. This AD was prompted by a report of a quality escape involving improper installation of counterweight retaining rings in the engine crankshaft counterweight groove during manufacture. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 15, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 23, 2023 (88 FR 11383, February 23, 2023).

The FAA must receive any comments on this AD by May 1, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**AD Docket:** You may examine the AD docket at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA-2023-0435; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above.

**Material Incorporated by Reference:**

- For Continental service information identified in this final rule, contact Continental Aerospace Technologies, Inc., 2039 South Broad Street, Mobile,

AL 36615; phone: (251) 308-9100; email: [MSB23Support@continental.aero](mailto:MSB23Support@continental.aero); website: [continental.aero](https://www.continental.aero).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA-2023-0435.

#### FOR FURTHER INFORMATION CONTACT:

Nicholas Reid, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5650; email: [nicholas.j.reid@faa.gov](mailto:nicholas.j.reid@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued AD 2023-04-08, Amendment 39-22355 (88 FR 11383, February 23, 2023) (AD 2023-04-08), for Continental GTSIO-520-C, -D, -H, -K, -L, -M, -N, and -S; IO-360-A, -AB, -AF, -C, -CB, -D, -DB, -E, -ES, -G, -GB, -H, -HB, -J, -JB, -K, and -KB; IO-470-D, -E, -G, -H, -J, -K, -L, -M, -N, -P, -R, -S, -T, -U, -V, and -VO; IO-520-A, -B, -BA, -BB, -C, -CB, -D, -E, -F, -J, -K, -L, -M, and -MB; IO-550-A, -B, -C, -D, -E, -F, -G, -L, -N, -P, and -R; LTSIO-360-E, -EB, -KB, and -RB; LTSIO-520-AE; O-470-A, -B, -E, -G, -H, -J, -K, -L, -M, -N, -R, -S, -T, and -U; TSIO-360-A, -AB, -B, -BB, -C, -CB, -D, -DB, -E, -EB, -G, -GB, -H, -HB, -JB, -KB, -LB, -MB, -RB, and -SB; TSIO-520-A, -AE, -AF, -B, -BB, -BE, -C, -CE, -D, -DB, -E, -EB, -G, -H, -J, -JB, -K, -KB, -L, -LB, -M, -NB, -P, -R, -T, -UB, -VB, and -WB; TSIO-550-A, -B, -C, -E, -G, -K, and -N; TSIOF-550-K; and TSIO-550-A, -B, and -C model reciprocating engines. AD 2023-04-08 required accomplishing the actions specified in paragraph III, Action Required, of Continental Aerospace Technologies, Inc. Mandatory Service Bulletin MSB23-01, Revision A, dated February 16, 2023 (MSB23-01A), except as discussed in "Exception to the Service Information." AD 2023-04-08 resulted from a report of a quality escape involving improper installation and inspection of counterweight retaining rings in the engine crankshaft counterweight groove during manufacture. AD 2023-04-08 also resulted from reports of two ground

engine seizures and one in-flight loss of engine oil pressure due to improper installation of the counterweight retaining rings during manufacture. The counterweight retaining rings are part of the engine crankshaft counterweight assembly retention system. Loosening of a counterweight retaining ring may result in the loss of retention of the counterweight. The FAA issued AD 2023-04-08 to prevent departure of counterweight and retaining hardware from the crankshaft assembly, which could result in loss of engine oil pressure, catastrophic engine damage, engine seizure, and consequent loss of the aircraft.

#### **Actions Since AD 2023-04-08 Was Issued**

Since the FAA issued AD 2023-04-08, the FAA has determined, and Continental has confirmed that IO-470-A, -C, -F, and -LO; TSIO-360-F; and TSIO-360-FB model reciprocating engines are also affected by the unsafe condition and should be added to the applicability. Additionally, the FAA determined that the limitations in the special flight permit paragraph, specifying no metal contamination in the oil filter, did not account for trace metal particles that may be found in newer engines due to break-in of the engine.

Accordingly, Continental IO-470-A, -C, -F, and -LO; TSIO-360-F; and TSIO-360-FB model reciprocating engines are added to the applicability paragraph of this AD. Also, the special flight permit paragraph of this AD has been revised, removing the limitation of "no metal contamination." The FAA is issuing this AD to address the unsafe condition on these products.

#### **Discussion of Final Airworthiness Directive**

##### **Comments on AD 2023-04-08**

The FAA received comments from seven individual commenters. The following presents the comments received on AD 2023-04-08 and the FAA's response to each comment.

#### **Request To Add Engine Models to Applicability**

Two individual commenters noted that there are engine models listed in the appendices of MSB23-01A that are omitted from the applicability of AD 2023-04-08.

The FAA agrees, and has revised the applicability paragraph of this AD to include Continental IO-470-A, -C, -F, and -LO; TSIO-360-F; and TSIO-360-FB model reciprocating engines.

#### **Request To Include Part Listing and Serial Numbers in the AD**

Two individual commenters requested that the list of affected parts and production dates should be included in the AD. Another individual commenter requested that the serial numbers of affected crankshafts and applicable manufacture date range of the affected engines should be included in the AD.

The FAA disagrees with the requests. MSB23-01A, which is incorporated by reference into this AD, contains the list of affected engines and crankshafts. Therefore, duplicating the appendix information from the service information into the AD is unnecessary. The FAA notes that paragraph (g)(2) of the required actions specifies "crankshaft assembly that was repaired or installed on or after June 1, 2021." The FAA did not change this AD as a result of this comment.

#### **Request To Correct Text in the Required Actions Paragraph**

One individual commenter stated that AD 2023-04-08 has incorrect language in the required actions, paragraph (g)(1), which reads; "(1) Crankshaft assembly having a crankshaft serial number listed in Appendix 1 of MSB23-01A; or". The commenter noted that Appendix 1 of MSB23-01A lists engine assembly serial numbers with associated installed crankshaft serial numbers.

The FAA disagrees that the language in paragraph (g)(1) is incorrect. MSB23-01A contains the affected engine serial numbers and crankshaft serial numbers, differentiated by engine model. The FAA did not change this AD as a result of this comment.

#### **Request To Review Labor Cost**

Two individual commenters stated that the \$85 labor rate in the estimated costs section of the AD is outdated. One commenter noted that the rate is well below the average shop rate for other trades, and suggested that by endorsing this rate, the FAA may be attracting less detail-oriented employees, thereby creating an unsafe condition.

The FAA disagrees. The FAA Office of Aviation Policy and Plans provides the labor rate of \$85 per work-hour for the FAA to use when estimating the labor costs of complying with AD requirements. The FAA did not change this AD as a result of this comment.

#### **Request To Include Cost of Individual Parts**

An individual commenter noted that costs of complete seal and gasket kits for each cylinder (valve cover, induction, push rods × 4, cylinder) are not

included in the cost estimate in AD-2023-04-08.

The FAA acknowledges the commenter's concerns. The FAA recognizes that in accomplishing the requirements of any AD, operators might incur "incidental" costs in addition to the "direct" costs that are reflected in the cost analysis presented in the AD. However, the cost analysis in ADs typically does not include incidental costs. No change was made to this AD regarding this issue.

#### **Request To Add Information on Cylinder Ring Seating**

An individual commenter stated they have a factory new Continental IO-470-N engine that is affected by this AD. The commenter stated their new motor was run at the factory before being shipped to them, so ring scoring had taken place. The commenter suggested that the AD might serve the impacted population by pointing out that cylinder rings may not seat. The commenter also expressed concern over the potential need to install new counterweight retaining rings on their factory new Continental IO-470-N engine.

The FAA disagrees with adding additional language to the AD regarding cylinder ring seating. The AD requires inspection of the counterweight retaining rings on affected engines using the referenced service information. MSB23-01A Paragraph III, note to paragraph 2(c) specifies that if counterweight retaining ring(s) are removed from the counterweight, new retaining ring(s) are required for reassembly. The FAA did not change this AD as a result of this comment.

#### **Revision of Special Flight Permit Paragraph**

The FAA revised the special flight permit paragraph of this AD by modifying the requirement to inspect the engine oil filter pleats or screen for evidence of metal contamination. The revised special flight permit paragraph in this AD requires that the engine first undergoes, or has undergone within the previous five flight hours, an oil change and filter/screen replacement that was accomplished by an appropriately rated mechanic or repair station, and any material found in the spent oil and oil filter pleats or oil screen has been evaluated to assess the engine's condition.

#### **FAA's Determination**

The FAA is issuing this AD because the agency determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

### Related Service Information Under 1 CFR Part 51

The FAA reviewed MSB23–01A. This service information specifies procedures for inspection of the crankshaft assembly for improper installation of the counterweight retaining rings in the counterweight, and corrective actions if improper installation is found. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

### AD Requirements

This AD requires accomplishing the actions specified in paragraph III, Action Required, of MSB23–01A, except as discussed in “Exception to the Service Information.”

### Differences Between This AD and the Service Information

The service information specifies compliance for engines with less than 200 operating hours, while this AD requires compliance for all affected engines, regardless of the operating hours. The FAA has determined that this unsafe condition, of improperly installed counterweight retaining rings, is likely to exist on affected engines. While the manufacturer’s service information excludes engines accumulating 200 or more operating hours, the FAA has not, as of yet, been provided with adequate data to support that exclusion. In the event the FAA receives data to support the exclusion of engines with more than 200 operating hours, or to make other changes to this AD, the FAA may consider further rulemaking.

The service information excludes Continental IO–470–A, –C, –F, and –LO; TSIO–360–F; and TSIO–360–FB model reciprocating engines from its list of affected engine models, while this AD includes these engines in the applicability paragraph.

### Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules

effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies foregoing notice and comment prior to adoption of this rule because the manufacturer discovered an assembly error for the affected engines. It is possible that one or more counterweight retaining rings were not properly seated in the crankshaft counterweight groove of the engine. This condition could allow the counterweight to depart from the crankshaft during engine operation. Because of the urgency of the unsafe condition, this AD requires inspection of any affected crankshaft assembly before further flight.

Since the FAA issued AD 2023–04–08, the FAA has determined, and Continental has confirmed that Continental IO–470–A, –C, –F, and –LO; TSIO–360–F; and TSIO–360–FB model reciprocating engines were inadvertently left off of the list of affected engine models in MSB23–01A. Due to this omission, Continental IO–470–A, –C, –F, and –LO; TSIO–360–F; and TSIO–360–FB model reciprocating engines with affected crankshafts were not captured by the applicability of AD 2023–04–08. Because the urgency of the unsafe condition applies to these additional model engines, this AD also requires inspection of the crankshaft assemblies on these engines before further flight, in addition to the population originally captured by AD 2023–04–08.

The manufacturing quality escape has resulted in ground engine seizures and an in-flight loss of engine oil pressure, which could lead to catastrophic engine damage, engine seizure, and consequent loss of the aircraft. Due to the low operational hours on the known crankshaft assembly failures, the short-term risk to the fleet is such that expeditious action must be taken and therefore this AD is effective upon publication.

Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B). In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

### Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2023–0435 and Project Identifier AD–2023–00384–E” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Nicholas Reid, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

**Costs of Compliance**

The FAA has revised the cost estimate of AD 2023–04–08 based on updated information from the manufacturer. The model engines added to the applicability of this superseding AD were accounted for in the cost estimate of AD 2023–04–08, as that cost estimate

was based on the list of affected engines and crankshafts in the appendices of MSB23–01A, not on the list of model engines in MSB23–01A.

The manufacturer has notified the FAA that 2,211 crankshaft assemblies are subject to the unsafe condition. The FAA estimates that of those 2,211 crankshaft assemblies, 1,659 are

installed on aircraft of U.S. registry. The FAA estimates that 553 engines will need to remove one cylinder, 553 engines will need to remove two cylinders, and 553 engines will need to remove three cylinders for compliance with this AD.

The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove one cylinder .....	10 work-hours × \$85 per hour = \$850	\$0	\$850	\$470,050
Remove two cylinders .....	18 work-hours × \$85 per hour = \$1,530.	0	1,530	846,090
Remove three cylinders .....	22 work-hours × \$85 per hour = \$1,870.	0	1,870	1,034,110
Inspect crankshaft counterweight retaining rings .....	0.75 work-hours × \$85 per hour = \$64.	0	64	106,176
Reposition, repeat, or remove/install counterweight assemblies.	1.5 work-hours × \$85 per hour = \$127.50.	0	127.50	211,522.50

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by:

■ a. Removing Airworthiness Directive 2023–04–08, Amendment 39–22355 (88 FR 11383, February 23, 2023); and

■ b. Adding the following new airworthiness directive:

**2023–05–16 Continental Aerospace Technologies, Inc.:** Amendment 39–22385; Docket No. FAA–2023–0435; Project Identifier AD–2023–00384–E.

**(a) Effective Date**

This airworthiness directive (AD) is effective March 15, 2023.

**(b) Affected ADs**

This AD replaces AD 2023–04–08, Amendment 39–22355 (88 FR 11383, February 23, 2023).

**(c) Applicability**

This AD applies to Continental Aerospace Technologies, Inc. (Continental) GTSIO–520–C, –D, –H, –K, –L, –M, –N, and –S; IO–360–A, –AB, –AF, –C, –CB, –D, –DB, –E, –ES, –G, –GB, –H, –HB, –J, –JB, –K, and –KB; IO–470–A, –C, –D, –E, –F, –G, –H, –J, –K, –L, –LO, –M, –N, –P, –R, –S, –T, –U, –V, and –VO; IO–520–A, –B, –BA, –BB, –C, –CB, –D, –E, –F, –J, –K, –L, –M, and –MB; IO–550–A, –B, –C, –D, –E, –F, –G, –L, –N, –P, and –R; LTSIO–360–E, –EB, –KB, and –RB; LTSIO–520–AE; O–470–A, –B, –E, –G, –H, –J, –K, –L, –M, –N, –R, –S, –T, and –U; TSIO–360–A, –AB, –B, –BB, –C, –CB, –D, –DB, –E, –EB, –F, –FB, –G, –GB, –H, –HB, –JB, –KB, –LB, –MB, –RB, and –SB; TSIO–520–A, –AE, –AF, –B, –BB, –BE, –C, –CE, –D, –DB, –E, –EB, –G, –H, –J, –JB, –K, –KB, –L, –LB, –M, –NB, –P, –R, –T, –UB, –VB, and –WB; TSIO–550–A, –B, –C, –E, –G, –K, and –N; TSIOF–550–K; and TSIOF–550–A, –B, and –C model reciprocating engines.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 8520, Reciprocating Engine Power Section.

**(e) Unsafe Condition**

This AD was prompted by a report of a quality escape involving improper installation of counterweight retaining rings in the counterweight groove during manufacture. The FAA is issuing this AD to prevent departure of counterweight and retaining hardware from the crankshaft assembly. The unsafe condition, if not addressed, could result in loss of engine oil pressure, catastrophic engine damage, engine seizure, and consequent loss of the aircraft.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Action**

For affected engines with an installed crankshaft assembly identified in paragraphs

(g)(1) or (2) of this AD, before further flight, do the actions identified in, and in accordance with paragraph III, Action Required, of Continental Mandatory Service Bulletin MSB23-01, Revision A, dated February 16, 2023 (MSB23-01A).

(1) Crankshaft assembly having a crankshaft serial number listed in Appendix 1 of MSB23-01A; or

(2) Crankshaft assembly that was repaired or installed on or after June 1, 2021, having a part number and crankshaft serial number listed in Appendix 2 of MSB23-01A.

#### (h) Exception to the Service Information

Where paragraph III.1.a. of MSB23-01A specifies actions for spare crankshaft assemblies, this AD does not require those actions.

#### (i) Parts Installation Prohibition

After the effective date of this AD, do not install on any engine a crankshaft assembly having a crankshaft serial number identified in Appendix 1 or Appendix 2 of MSB23-01A, unless the actions required by paragraph (g) of this AD have first been accomplished for that crankshaft assembly.

#### (j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Continental Mandatory Service Bulletin MSB23-01, dated February 13, 2023.

#### (k) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to only permit a one-time, non-revenue ferry flight to operate the aircraft to a location where the maintenance actions can be performed, provided that the engine first undergoes, or has undergone within the previous five flight hours, an oil change and filter/screen replacement that was accomplished by an appropriately rated mechanic or repair station, and any material found in the spent oil and oil filter pleats or oil screen has been evaluated to assess the engine's condition.

#### Note 1 to paragraph (k) of this AD:

Guidance for accomplishing the actions required by paragraph (k) of this AD can be found in Section 6-4.8.2 and Section 6-4.8.5.1 of Continental Aerospace Technologies Standard Practice Maintenance Manual, Revision 1, Change 3, dated January 6, 2023 (also known as M-0).

#### (l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (m)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (m) Related Information

(1) For more information about this AD, contact Nicholas Reid, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5650; email: [nicholas.j.reid@faa.gov](mailto:nicholas.j.reid@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(4) and (5) of this AD.

#### (n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on February 23, 2023 (88 FR 11383, February 23, 2023).

(i) Continental Aerospace Technologies, Inc. Mandatory Service Bulletin MSB23-01, Revision A, dated February 16, 2023.

(ii) [Reserved]

(4) For Continental service information identified in this AD, contact Continental Aerospace Technologies, Inc., 2039 South Broad Street, Mobile, AL 36615; phone: (251) 308-9100; email: [MSB23Support@continental.aero](mailto:MSB23Support@continental.aero); website: [continental.aero](http://continental.aero).

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on March 9, 2023.

#### Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-05339 Filed 3-13-23; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Parts 43, 65, and 147

[Docket No.: FAA-2021-0237; Amdt. No. 43-52A, 65-63A, 147-9A]

RIN 2120-AL67

#### Aviation Maintenance Technician Schools

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation.

**ACTION:** Interim final rule; reopening of comment period for regulatory impact analysis only.

**SUMMARY:** This action reopens the comment period for the regulatory evaluation associated with the FAA's interim final rule, *Aviation Maintenance Technician Schools*, which was published in the **Federal Register** on May 24, 2022. The regulatory evaluation associated with this rule was not posted to the docket prior to the close of the comment period. Therefore, the FAA is reopening the comment period to allow the public the opportunity to adequately analyze the full regulatory evaluation of the interim final rule. The FAA will accept comments on the regulatory evaluation only and not on the regulatory changes in the interim final rule.

**DATES:** The comment period for the interim final rule published on May 24, 2022 (87 FR 31391), closed on June 23, 2022, is reopened until April 14, 2023.

**ADDRESSES:** You may send comments identified by docket number FAA-2021-0237 using any of the following methods:

- *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations, M-30; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at 202-493-2251.

*Privacy:* In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments,